
CITY OF BALTIMORE WET SMOKE AND DYED I	Page 1 of 3			
Sewershed: Low Level Subsewershed: 44	Company: REI/DRAYCO	Date: 08/26/2008		
Test Type: Smoke	Ground Condition: Dry: X Damp:_ Wet:_	Supervisor: E.R. Crew: 04		
Manhole ID: S17M005MH	Test ID: 1029-560	Notifications Made:X Residents, Fire, 311		
Field Skatch: (Show all manhalos with nun	phore blower placement location, candbag or ico	ation locations street names huilding addresses		

Field Sketch: (Show all manholes with numbers, blower placement location, sandbag or isolation locations, street names, building addresses and locations, defect locations and photograph numbers)



CITY OF BALTIMORE WET WEATHER CONSENT DECREE SMOKE AND DYED WATER TESTING FORM						Page 2 of 3					
;	Sewershed: Low Level Subsewershed: 44	Company: REI/DRAYCO					Date: 08/26/2008				
	Test Type: Smoke	Ground Condition: Dry: X Damp:_ Wet:_				Supervisor: E.R. Crew: 04					
Ма	nhole ID: S17M005MH	Test ID: 1029-560				Notifications Made:X Residents, Fire, 311					
Field Sketch: (Show all manholes with numbers, blower placement location, sandbag or isolation locations, street names, building addresses and locations, defect locations and photograph numbers)											
Defect No.		Source Type		on Sector	Drai	nage ea			Photo Number		
1	2449 FREDERICK AVE.	03	01	02	_	1	03		1029-560_OB01-01.jpg		
					-						
					-						
					-						
					1						
		OB	SERVA	ATION CC	DES						
	Source Type	l	Location			5	Sector	1	Severity		
01 Ma	ain Sewer 10 MH Frame	01 Paved C			aved		Public	01	No Smoke		
	rvice Line 11 Storm Drain	02 Asphalt		1 Field/W		02	Private		Trace		
	eanout 12 Catch Basin	03 Paved 0						03	Moderate		
	wnspout 13 Storm MH	04 Drivewa	y 1	3 Golf Co	ourse			_	Major		
05 Are	ea Drain 14 Storm Ditch	05 Sidewal	k 1	4 Other							
	vy. Drain 15 Excavation	06 Curb									
	air. Drain 16 Water Line	07 Yard - F									
08 Found. Drai 17 Tele. Pole		08 Yard - B									
09 Blo	dg. Interio 18 Other	09 Yard - S	ide					Ш_			

PAGE 3 of 3

CITY OF BALTIMORE SMOKE TESTING OBSERVATION SUMMARY LOW LEVEL SEWERSHED

BALTIMORE CITY PROJECT 1029 REI/DRAYCO

Unique Test ID: 560 Date: 08/26/2008 Basin: LL - 44 Manhole ID: S17M_005MH Defect No: OB01 Supervisor: E.R. Crew: 04 Dye Test Recommended: N


Location: 2449 FREDERICK AVE.

Source Type: 03 Cleanout Sector: 02 Private

Location: 01 Paved Concrete Severity: 03 Moderate Drainage Area: 1

Comments: AT GRADE CLEANOUT MISSING CAP.

SMOKE TEST PHOTOGRAPHS



Photograph No: OB01-01 Filename: 1029-560_OB01-01.jpg